


**COPY**



**DATE:** September 22, 2003

**TO:** King County International Airport Tenants  
distributed by e-mail and fax

**FROM:**   
Robert I. Burke, AAE, Airport Director

**SUBJECT:** **CHANGE IN CLOSURE TIME FOR SEPTEMBER 23 (TUESDAY)**

For **September 23, 2003 (Tuesday)**, the **first 5400 feet closed** of **Runway 31L** (main runway) from **10:30 - 15:30 (local time)**. Additionally, taxiway intersections A9 and B5 will be closed and Runway 31L PAPI and REILs will be out of service. If in a south or north flow, there will be 4601 feet available for arrival and departure.

**ATTENTION**

The partial closure of Runway 31L will be from  
**10:30 - 15:30 (local time) on September 23, 2003 (Tuesday).**

**THIS WORK IS WEATHER DEPENDENT.**

**PLEASE CHECK NOTAMS DAILY FOR CHANGES.**